



**Ministry of Health and
Long-Term Care**

**Inspection Report under
the Long-Term Care
Homes Act, 2007**

**Ministère de la Santé et des
Soins de longue durée**

**Rapport d'inspection sous la
Loi de 2007 sur les foyers de
soins de longue durée**

**Health System Accountability and
Performance Division
Performance Improvement and
Compliance Branch**

**Division de la responsabilisation et de la
performance du système de santé
Direction de l'amélioration de la
performance et de la conformité**

**Hamilton Service Area Office
119 King Street West, 11th Floor
HAMILTON, ON, L8P-4Y7
Telephone: (905) 546-8294
Facsimile: (905) 546-8255**

**Bureau régional de services de
Hamilton
119, rue King Ouest, 11^{ième} étage
HAMILTON, ON, L8P-4Y7
Téléphone: (905) 546-8294
Télécopieur: (905) 546-8255**

Public Copy/Copie du public

Report Date(s) / Date(s) du Rapport	Inspection No / No de l'inspection	Log # / Registre no	Type of Inspection / Genre d'inspection
Oct 15, 2013	2013_189120_0072	H-000102- 13	Other

Licensee/Titulaire de permis

JOHN NOBLE HOME
97 Mt. Pleasant Street, BRANTFORD, ON, N3T-1T5

Long-Term Care Home/Foyer de soins de longue durée

JOHN NOBLE HOME
97 MOUNT PLEASANT STREET, BRANTFORD, ON, N3T-1T5

Name of Inspector(s)/Nom de l'inspecteur ou des inspecteurs

BERNADETTE SUSNIK (120)

Inspection Summary/Résumé de l'inspection



The purpose of this inspection was to conduct an Other inspection.

This inspection was conducted on the following date(s): October 10, 2013

The purpose of the visit was to conduct a post occupancy review of the newly built 3 story addition which was added to the existing home and completed in February 2013.

During the course of the inspection, the inspector(s) spoke with the administrator, director of care, housekeeping/laundry supervisor and maintenance person.

During the course of the inspection, the inspector(s) toured all three floors including the laundry room, service corridors, common areas, resident rooms and outdoor spaces, tested the resident-staff communication and response system and stairwell and perimeter door alarms and locks.

The following Inspection Protocols were used during this inspection:
Safe and Secure Home

There are no findings of Non-Compliance as a result of this inspection.

NON-COMPLIANCE / NON - RESPECT DES EXIGENCES	
Legend	Legendé
WN – Written Notification	WN – Avis écrit
VPC – Voluntary Plan of Correction	VPC – Plan de redressement volontaire
DR – Director Referral	DR – Aiguillage au directeur
CO – Compliance Order	CO – Ordre de conformité
WAO – Work and Activity Order	WAO – Ordres : travaux et activités



Non-compliance with requirements under the Long-Term Care Homes Act, 2007 (LTCHA) was found. (A requirement under the LTCHA includes the requirements contained in the items listed in the definition of "requirement under this Act" in subsection 2(1) of the LTCHA.)

The following constitutes written notification of non-compliance under paragraph 1 of section 152 of the LTCHA.

Le non-respect des exigences de la Loi de 2007 sur les foyers de soins de longue durée (LFSLD) a été constaté. (Une exigence de la loi comprend les exigences qui font partie des éléments énumérés dans la définition de « exigence prévue par la présente loi », au paragraphe 2(1) de la LFSLD.

Ce qui suit constitue un avis écrit de non-respect aux termes du paragraphe 1 de l'article 152 de la LFSLD.

Issued on this 15th day of October, 2013

Signature of Inspector(s)/Signature de l'inspecteur ou des inspecteurs

B Sosnik